EXHIBIT 3

APPRAISAL AWA<u>RD</u>

Insured:

Coral Realty LLC

Date of Loss:

December 5, 2012

Insurer:

Federal Insurance Company

Policy #:

009 9836120 00

Claim #:

YORK # CHME-0707A9

Insured Location:

201 East 14th Street (129 3rd Ave.), NY, NY

We the UNDERSIGNED, pursuant to our appointment as Appraisers and/or Umpire, in the matter of appraisal for the loss to a commercial apartment building and retail operation, caused by an incident occurring on or about December 5th, 2012, DO HEREBY CERTIFY that we have truly and conscientiously performed the duties assigned to us in this appraisal involving the above listed policy of insurance.

WE DO HEREBY CERTIFY that, over the course of approximately one year, we have heard and seen all of the evidence offered by both the insured and the insurer. including multiple proposed scopes of work and methodologies for the work, and at least two site visits by the Appraisers and Umpire along with site visits by agents of the Appraisers and Umpire, and have appraised and determined the amount of loss as follows:

PROPERTY LOSS, EXTRA EXPENSES INCURRED and POTENTIAL LOSS of RENTS and OTHER RELATED EXPENSES TO BE INCURRED (Spreadsheets attached for details of AWARD)

Coverage	Replacement Cost	Depreciation	Actual Cash Value
Building		No Betterment	\$ 5, 328,016.00
Extra Expenses Incurred	1		\$ 200,850.00
Loss of Rents and Other	Related Expenses		As Incurred*
TOTALS			\$ 5,528,866.00

(*This element of the Appraisal Award is for loss of rental income during the period of repair and related reasonable and necessary expenses incurred during the repairs process.)

We do hereby designate the foregoing sums as our Appraisal Award. The above award reflects the agreed physical damages and projected repair costs associated with the commercial apartment building and retail space at 201 East 14th Street (129 3rd Ave.), NY, NY. The amounts are **NOT** subject to deduction for any previous payments or policy

· mo?

deductible. Previous payments were for emergency repairs and the deductible was applied to those emergency repairs. The building damage is a repair to a small part of the building and therefore not subject to depreciation as there was no betterment to the building.

The attachments to this **Appraisal Award** support our determination of the building and extra expenses VALUE OF THE LOSS. Loss of rents, tenant moving costs and other reasonable related costs are to be given due consideration by the Insurer as incurred.

Appraiser for the Insured

Date signed

Appraiser for the Insurer

Date signed

Umpire

Date signed

Item	Line #'s	Claim - 3/26	MDY
Electrical	322, 323	214,135	190,000
Exterior/General	282	13,500	13500
Exterior Stairway	293, 316	660,624	400,000
Demolition - Front	292	131,656	110,000
Demo- N wall	306,	804,566	725,000
Demolition - Equip, Materials etc	307, 340, 341	105,166	50,000
Demolition - Remove Stairway	321	219,427	100,000
Left elevation	284-86, + 308	1,042,995	900,000
HVAC	291 + 320	541367	500,000
Debris Removal	280	96,000	75,000
Scaffolding	271	512,500	300,000
Post-Construction Clean-up	273+274	314,620	225,000
Off-site storage	309	24,765	24,765
Site work/Excavation	333	125,000	25,000
Concrete Foundation	334	28,500	0
General Conditions	277 - 79, 342	788,081	500,000
SUB-TOTAL		5,622,902	4,138,265
P and OH s	20.00%	1,124,580	827,653
Tax	8.88%	492,003	362,098
Total		7,239,485	5,328,016

ROLLINS

ACCOUNTING &
INVENTORY
SERVICES, INC.

Coral Crystal, LLC Loss Summary

Date of Loss: December 5, 2012

Schedule 1

Description	Reference	 Amount
Lost Rent	Schedule 2	\$ 81,240
Plus: Extra Expenses 1) Hotel Rooms for Displaced Tenants 2) Moving Fees for Displaced Tenants 3) Incurred Expenses Subtotal	Schedule 3 \$2k per Tenant Schedule 4	486,000 72,000 - 558,000
TOTAL		\$ 639,240

Notes

1) We reserve the right to update and/or amend as required.

ROLLINS
ACCOUNTING &
INVENTORY
SERVICES, INC.

Coral Crystal, LLC

Lost Rent

Date of Loss: December 5, 2012

Schedule 2

Unit #	Sq. Ft.	% of Total	Annual Rent 09/01/17 - 08/31/18	verage ily Rent	Days Offline	L	ost Rent
207	868	0.88%	55,063	\$ 150.44	90		13,540
307	868	0.88%	55,063	150.44	90		13,540
407	868	0.88%	55,063	150.44	90		13,540
507	868	0.88%	55,063	150.44	90		13,540
607	868	0.88%	55,063	150.44	90		13,540
707	868	0.88%	55,063	150.44	90		13,540
Total	98,522	100.00%	\$ 6,249,865	\$ 17,076		\$	81,240
					Total	\$	81,240

Source: Lease.

ROLLINS

ACCOUNTING &
INVENTORY
SERVICES, INC.

Coral Crystal, LLC Hotel Rooms for Displaced Tenants Date of Loss: December 5, 2012

Schedule 3

Hotel Rooms for Displaced Tenants:

Number of Rooms/Suites Displaced	6
Tenants per Room/Suite	 6
Total Number of Tenants Displaced	36
Amount of Hotel Rooms Needed with 2 Tenants per Hotel Room	18_
Nights Displaced	90
Hotel Room Nights	1,620
Hotel Room Rate (Note 1)	300
Total Hotel Room Charges	\$ 486,000

Notes:

- 1) NYU has an agreed rate with Affinia Hotel Collection of \$300/night.
- 2) The above calculation is based on estimates. We reserve the right to update and/or amend once incurred.

ROLLINS
ACCOUNTING &
INVENTORY

Schedule 5

Page 1 of 3

Coral Ci	rystal, LLC							
	d Expenses							
		- F 0040						
ate or	Loss: December	er 5, 2012						
	Involes	Cauraa					Invelor	A ma a comb
Ref. #	Invoice Date	Source Document	Investor #	Vendor	Description		Invoice Amount	Amount Awarded
1 1	01/28/13	Invoice	Invoice #	A & B Engineering & Land Surveying, P.C.	Description Prepare survey for encroachments.	\$	1,500.00	Awarded
2	01/26/13	Invoice	N/A	A & B Engineering & Land Surveying, P.C. A & B Engineering & Land Surveying, P.C.	Survey for Property Line/Meeting	\$	2,500.00	
3	02/18/13	Invoice	13446	A & B Engineering & Land Surveying, P.C. A & B Engineering & Land Surveying, P.C.	Survey for Property Line/Court Appearance	\$	1.600.00	
4	05/22/13	Invoice	13784	A & B Engineering & Land Surveying, P.C. A & B Engineering & Land Surveying, P.C.	4 Days Work @ 2,000.00 per day/Slab Location	\$	9,000.00	
	03/22/13	IIIVOICE	13704	A & B Eligineering & Land Surveying, F.C.	Subtotal	\$	14,600.00	\$ 14,600.00
					Gustotai	Ψ	14,000.00	\$ 14,000.00
5	02/04/13	Invoice	Bill # 13-1	Darius Toraby Architects, P.C.	Fees for Expert Testimony, etc.	\$	3,500.00	
6	02/04/13	Invoice	Bill # 13-2	Darius Toraby Architects, P.C.	Fees for Expert Testimony, etc.	\$	11,287.50	
7	02/11/13	Invoice	Bill # 13-3	Darius Toraby Architects, P.C.	Fees for Expert Testimony, etc.	\$	6,558.50	
8	02/18/13	Invoice	Bill # 13-4	Darius Toraby Architects, P.C.	Fees for Expert Testimony, etc.	\$	1,260.39	
9	04/15/13	Invoice	Bill # 13-5	Darius Toraby Architects, P.C.	Fees for Expert Testimony, etc.	\$	1,487.50	
	2 100				Subtotal	\$	24.093.89	None
	++		1			1	2.,000.00	
39	02/18/13	Invoice	294	SR Harwood Consulting Engineering PC	Structural Engineering from 2/18/13 to 4/16/13	\$	3,250.00	
40	02/19/13	Invoice	125	SR Harwood Consulting Engineering PC	Services Rendered	\$	12,000.00	
41	05/14/13	Invoice	302	SR Harwood Consulting Engineering PC	Engineering Retainer for Period Beg. 4/16/13	\$	5,000.00	
42	10/11/13	Invoice	361	SR Harwood Consulting Engineering PC	Engineering Retainer for 6/1/13 to Date	\$	5,000.00	
43	12/11/13	Invoice	400	SR Harwood Consulting Engineering PC	Engineering for Structural Period 10/11/13 to 1/1/14	\$	3,750.00	
44	02/06/14	Invoice	411	SR Harwood Consulting Engineering PC	Engineering for Structural Period 1/1/14 to 3/1/14	\$	3,750.00	
45	07/31/14	Invoice	447	SR Harwood Consulting Engineering PC	Engineering for Structural Period May to Sep 1, 2014	\$	3,750.00	
46	10/06/14	Invoice	460	SR Harwood Consulting Engineering PC	Engineering for Structural Period 9/1/14 to 11/1/14	\$	3,750.00	
47	12/02/14	Invoice	460	SR Harwood Consulting Engineering PC	Engineering for Structural Period 11/1/14 to 12/31/14	\$	3,750.00	
48	08/31/15	Invoice	531	SR Harwood Consulting Engineering PC	Structural Engineering for Period Moving Forward 8-31-15	\$	3,750.00	
49	04/15/16	Invoice	588	SR Harwood Consulting Engineering PC	Structural Engineering for 12/31/15 to 4/15/16	\$	5,000.00	
50	12/01/16	Invoice	201612	SR Harwood Consulting Engineering PC	Engineering Services	\$	3,500.00	
51	05/24/17	Invoice	684	SR Harwood Consulting Engineering PC	Structural Engineering for 4/15/16 to 5/24/17	\$	5,000.00	
52	10/19/17	Invoice	699	SR Harwood Consulting Engineering PC	Structural Engineering for 5/24/17 to Date	\$	3,500.00	
53	01/10/18	Invoice	701	SR Harwood Consulting Engineering PC	Structural Engineering for Period this Period - 16 hrs @ \$300	\$	4,800.00	
					Subtotal	\$	69,550.00	\$ 61,250.00
							,	
54	02/17/15	Invoice	1463-1	C3D Architecture PLLC	Architect fees.	\$	24,360.00	
55	04/17/13	Invoice	307407129	Iceberg Developing Co., LLC	Installation of New Wall	\$	36,000.00	
56	05/04/15	Invoice	200603	Iceburg Developing Co., LLC	Moving Students/Removing Furniture/Install Wall	\$	44,312.50	
	02/20/18	Invoice	201700	Iceburg Developing Co., LLC	Meetings with engineers, architects, insurer, etc.	\$	165,000.00	
57	04/19/13	Invoice	RTS13-123	Redeye Technical Services, Inc.	Location Survey (\$3,500 Discounted to \$3,000)	\$	3,000.00	
58	01/14/13	Invoice	22613	Wexler Associates	Field Visit/Prepared Report	\$	4,200.00	
59	01/31/13	Invoice	22628	Wexler Associates	Field Visit/Prepared Report	\$	7,000.00	
					Subtotal	\$	283,872.50	\$ 125,000.00
					TOTALS	\$	392,116.39	\$ 200,850.00
					TOTALS		\$	\$ 392,116.39

ACCOUNTING &
INVENTORY
SERVICES INC

Schedule 5

Page 2 of 3

oral Crys	stal, LLC						
urred E	stal, LLC Expenses ess: Decemb						
te of Lo	ss: Decemb	er 5, 2012					
	Invoice	Source				Invoice	Amount
Ref. #	Date	Document	Invoice #	Vendor	Description	Amount	Amount Awarded
							+
	 						++
	+	+					++
	+						++
							+
							++
							++
							11
							+
							+
						1.1	

ROLLINS

Accounting &
INVENTORY
SERVICES, INC.

Schedule 5

							1 1
Coral Crys	stal, LLC						
ncurred E	Expenses						
Date of Lo	Expenses oss: Decemb	er 5, 2012					
	Invoice	Source				Invoice	Amount
Ref. #	Date	Document	Invoice #	Vendor	Description	Amount	Awarded

Page 3 of 3

Client: Coral Realty LLC. Coral Crystal LLC

Property: 201 East 14th Street

New York, NY 10003

Operator Info:

Operator: KWILSON

Estimator: Ken Wilson Business: (631) 445-0042

Company: ACNY Developers Inc. Business: 618 Columbus Avenue

New York, NY 10024

Reference: Bill Cook Business: (212) 501-0505

Position: Owner

Company: ACNY Developers Inc.
Business: 618 Columbus Avenue
New York, NY 10024

Type of Estimate:

Price List: NYMN7X FEB18

Labor Efficiency: Restoration/Service/Remodel

Estimate: CORALR-04-15-01

This estimate is based on my visual inspection of the damages on 04/26/2015. Any additional damages discovered thereafter will be addressed in a supplemental estimate.

This Estimate is based on current market conditions (changes in supply and/or changes in demand for labor, supply, equipment and/or or energy that cause relatively short-term cost and/or schedule variations) existing as of the date of this Estimate for labor, supply, equipment and/or or energy (electric, gas, oil, etc.). Due to the ever-changing market conditions, the prices set forth in this Estimate are good only for a period of 180 days from the date of this Estimate. Notwithstanding the same, where the price of material, labor, equipment, and/or energy increases significantly -- meaning a change in price within 180 days from the date of this Estimate by an amount exceeding 10 percent -- said price shall be equitably adjusted.

ACNY Developers uses Xactimate®, a software system for estimating the cost of repairs and reconstruction for residential and commercial structures as a tool. Based on market conditions, site conditions and/or contractors risk, additional scope items may be added to the existing database, and/or items may be modified including description and price, to reflect these conditions.

Except as may be specifically included in this Estimate, the following are excluded from this Estimate, and if later included, this Estimate scope and price shall be equitably adjusted:

- · Code or ADA upgrade work
- · Content manipulation, removal or disposal
- · Extensions or additions to existing footprint of building
- Mold or asbestos testing or remediation
- · Lead abatement or testing of same
- Security system(s) or monitoring
- Utility service charges
- Foundation or concrete slab repairs
- · Overtime, weekend, or holiday hours

Case 1:17-cv-01007-DAB-BCM Document 35-3 Filed 12/21/18 Page 12 of 72

A.C.N.Y. Developers

- · Additional living expenses
- · Any/All emergency service work performed to date
- · Private Security
- · Clean up or disposal of hazardous materials
- · Repairs to landscaping, driveways, or sidewalks caused by either the loss or during construction
- · Applicable Federal, State and/or local taxes
- · Unforeseen damage or pre-existing structural conditions

As conditions dictate, we hereby reserve the right to amend this Estimate as necessary throughout the adjustment process.

CORALR-04-15-01 Main Level


Lobby				Height: 12' 8"
	1,265.14 SF Walls		451.83 SF Ceiling	
	1,716.97 SF Walls & Ceiling		451.83 SF Floor	
	50.20 SY Flooring		97.51 LF Floor Per	imeter
1	102.51 LF Ceil. Perimeter			
Door	1' 6" X 1' 6"	Opens into	CHUTE	
Door	2' 6" X 6' 8"	Opens into	EXIT_HALLWAY	
Missing Wall - Goes to Floor	5' X 6' 8"	Opens into	MAIL_ROOM	
Door	2' 6" X 6' 8"	Opens into	Exterior	
Door	2' 6" X 6' 8"	Opens into	Exterior	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
1. R&R 5/8" drywall - hung, taped, floated, ready for paint	463.54 SF	0.63	2.86	1,617.75
2. R&R Cove base molding - rubber or vinyl, 2 1/2" high	36.42 LF	0.45	1.89	85.22
3. R&R Metal studding, 6" wide, 16" OC, 25 gauge	462.12 SF	0.65	2.50	1,455.68
4. R&R Chair rail - oversized - 3 1/4"	36.42 LF	0.63	3.75	159.52
5. R&R Base cap	36.42 LF	0.25	1.88	77.58
6. R&R Marble base - High grade	36.42 LF	3.21	22.06	920.34
7. Mask and prep for paint - plastic, paper, tape (per LF)	102.51 LF	0.00	1.54	157.87
8. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	1,716.97 SF	0.00	1.73	2,970.36
9. Paint chair rail - two coats	97.51 LF	0.00	1.63	158.94
10. Seal & paint base cap	97.51 LF	0.00	0.90	87.76
11. Clean and deodorize carpet	451.83 SF	0.00	0.42	189.77
Totals: Lobby				7,880.79

Totals: Exit Hallway


Exit Hally	vay			Height: 9'
3 11	184.73 SF Walls		31.99 SF Ceiling	
T Exit Halfway to Eleva	216.72 SF Walls & Ceiling		31.99 SF Floor	
	3.55 SY Flooring		20.42 LF Floor Pe	erimeter
	24.33 LF Ceil. Perimeter			
Door	2' 6" X 6' 8"	Opens in	to LOBBY	
Subroom:	Exit offset (1)			Height: 8' 9"
TE	87.50 SF Walls		24.15 SF Ceiling	
n = n Stainwell Δ	111.65 SF Walls & Ceiling		24.15 SF Floor	
To Stairwell A	2.68 SY Flooring		10.00 LF Floor Pe	erimeter
	13.92 LF Ceil. Perimeter			
- 3' 11" -				
Door	2' 6" X 6' 8"	Opens in	to Exterior	
Missing Wall	3' 11" X 8' 9"	Opens in	to EXIT_HALLWAY	
Missing Wall	5' 9" X 8' 9"	Opens in	to STAIRWELL_A	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
12. R&R 5/8" drywall - hung, taped, floated, ready for paint	148.28 SF	0.63	2.86	517.50
13. R&R Cove base molding - rubber or vinyl, 2 1/2" high	14.92 LF	0.45	1.89	34.91
14. R&R Metal studding, 6" wide, 16" OC 25 gauge	c, 134.25 SF	0.65	2.50	422.89
15. Remove Emergency lighting - battery Commercial	- 1.00 EA	19.05	0.00	19.05
16. (Install) Emergency lighting - battery - Commercial	1.00 EA	0.00	76.86	76.86
17. Mask and prep for paint - plastic, pape tape (per LF)	er, 38.25 LF	0.00	1.54	58.91
18. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	328.36 SF	0.00	1.73	568.06
19. Paint door or window opening - 2 coat (per side)	2.00 EA	0.00	34.81	69.62
20. Paint door slab only - 2 coats (per side	2.00 EA	0.00	40.71	81.42
21. Paint concrete the floor	56.13 SF	0.00	1.01	56.69

CORALR-04-15-01 3/26/2018 Page: 4

1,905.91



Second Floor




CONTINUED - Stair A Hall

Subroom: E	xit Hall (2)			Height: 8
	218.00 SF Walls		42.10 SF Ceiling	
	260.10 SF Walls & Ceiling		42.10 SF Floor	
REDICTION OF Back Bedroom Min	4.68 SY Flooring		27.25 LF Floor Peri	meter
3'7".4	27.25 LF Ceil. Perimeter			
Door	2' 6" X 6' 8"	Opens into	OPEN	
Missing Wall	3' 7" X 8'	Opens into	STAIR_A_HALL	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
29. R&R 5/8" drywall - hung, taped, floated, ready for paint	234.25 SF	0.63	2.86	817.54
30. R&R Cove base molding - rubber or vinyl, 2 1/2" high	25.92 LF	0.45	1.89	60.65
31. R&R Metal studding, 6" wide, 16" OC, 25 gauge	207.33 SF	0.65	2.50	653.09
32. Mask and prep for paint - plastic, paper, tape (per LF)	61.14 LF	0.00	1.54	94.16
33. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	550.83 SF	0.00	1.73	952.94
34. Paint door or window opening - 2 coats (per side)	2.00 EA	0.00	34.81	69.62
35. Paint door slab only - 2 coats (per side)	2.00 EA	0.00	40.71	81.42

Totals: Stair A Hall 2,729.42

Height: 12' 6"



Missing Wall	5' 9" X 12' 6"	Opens into		
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
36. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
37. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
38. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
CODALD 04 15 01			2/26/2010	D

CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
39. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
40. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
41. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side o	f each flight			
42. Paint concrete the floor	43.67 SF	0.00	1.01	44.11

Totals: Stair A 1,790.02


Hallway				Height: 8'
	1,761.78 SF Walls		490.33 SF Ceiling	
Chipat (1)	2,252.11 SF Walls & Ceiling		490.33 SF Floor	
State A Annual Main Rectangle (17) 1 7	54.48 SY Flooring		224.60 LF Floor Period	meter
	224.60 LF Ceil. Perimeter			
Door	2' 6" X 6' 8"	Opens into S	STAIR_A_HALL	
Door	2' 6" X 6' 8"	Opens into T	ΓEL_CLST	
Door	2' 6" X 6' 8"	Opens into I	MAIN_ROOM	
Door	2' 6" X 6' 8"	Opens into S	STAIR_B	
Door	2' 6" X 6' 8"	Opens into A	APT_F	
Door	2' 6" X 6' 8"	Opens into A	APT_E	
Door	2' 6" X 6' 8"	Opens into A	APT_D	
Door	2' 6" X 6' 8"	Opens into A	APT_C	
Door	2' 6" X 6' 8"	Opens into A	APT_B	
Door	2' 6" X 6' 8"	Opens into A	APT_A	
Window	7' 3" X 4' 10"	Opens into l	Exterior	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
43. R&R 5/8" drywall - hung, taped, floated, ready for paint	126.00 SF	0.63	2.86	439.74
44. R&R Chair rail - 2 1/2"	16.50 LF	0.63	3.41	66.67
45. R&R Baseboard - 3 1/4"	16.50 LF	0.69	3.52	69.47
46. R&R Metal studding, 6" wide, 16" OC, 25 gauge	58.50 SF	0.65	2.50	184.28
47. Remove Emergency lighting - battery - Commercial	1.00 EA	19.05	0.00	19.05

CONTINUED - Hallway

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
48. (Install) Emergency lighting - battery - Commercial	1.00 EA	0.00	76.86	76.86
49. Mask and prep for paint - plastic, paper, tape (per LF)	224.60 LF	0.00	1.54	345.88
50. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	2,252.11 SF	0.00	1.73	3,896.15
51. Paint door or window opening - 2 coats (per side)	10.00 EA	0.00	34.81	348.10
52. Paint door slab only - 2 coats (per side)	10.00 EA	0.00	40.71	407.10
53. Paint chair rail - two coats	224.60 LF	0.00	1.63	366.10
54. Paint baseboard - two coats	224.60 LF	0.00	1.63	366.10
55. Clean floor, strip & wax	490.33 SF	0.00	0.82	402.07
Totals: Hallway				6,987.57

Total: Second Floor 11,507.01


Third Floor



Door	2' 6" X 6' 8"	Opens into	HALLWAY	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
56. R&R 5/8" drywall - hung, taped, floated, ready for paint	128.24 SF	0.63	2.86	447.56
57. R&R Cove base molding - rubber or vinyl, 2 1/2" high	14.00 LF	0.45	1.89	32.76
58. R&R Metal studding, 6" wide, 16" OC, 25 gauge	112.00 SF	0.65	2.50	352.80
59. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
60. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
61. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
ORALR-04-15-01			3/26/2018	Page:

CONTINUED - Stair A Hall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
62. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71
Totals: Stair A Hall				1.515.31



Stair A Height: 12' 6"

289.70 SF Walls 333.36 SF Walls & Ceiling 4.85 SY Flooring

26.86 LF Ceil. Perimeter

43.67 SF Ceiling 43.67 SF Floor

21.11 LF Floor Perimeter

Missing Wall 5' 9" X 12' 6"

Ope	ns into	STAIR	A E	IALL

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
63. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
64. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
65. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
66. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
67. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
68. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side of	of each flight			
69. Paint concrete the floor	43.67 SF	0.00	1.01	44.11

Totals: Stair A 1,790.02


Totals: Hallway

Hallway				Height: 8'
	1,761.78 SF Walls		490.33 SF Ceiling	
Seria Sedroson (7)	2,252.11 SF Walls & Ceiling		490.33 SF Floor	
State Annual Control of the Art o	54.48 SY Flooring		224.60 LF Floor Peri	meter
To Hunter the Burg of the Burg	224.60 LF Ceil. Perimeter			
Door	2' 6" X 6' 8"	Onone into	STAIR A HALL	
Door	2' 6" X 6' 8"	•	MAIN ROOM	
Door	2' 6" X 6' 8"	Opens into	_	
Door	2' 6" X 6' 8"	Opens into	-	
Door	2' 6" X 6' 8"	Opens into	-	
Door	2' 6" X 6' 8"	Opens into	-	
Door	2' 6" X 6' 8"	Opens into	_	
Door	2' 6" X 6' 8"	Opens into	_	
Door	2' 6" X 6' 8"	Opens into	_	
Window	7' 3" X 4' 10"	Opens into	_	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
70. R&R 5/8" drywall - hung, taped, floated, ready for paint	126.00 SF	0.63	2.86	439.74
71. R&R Chair rail - 2 1/2"	16.50 LF	0.63	3.41	66.67
72. R&R Baseboard - 3 1/4"	16.50 LF	0.69	3.52	69.47
73. R&R Metal studding, 6" wide, 16" OC, 25 gauge	58.50 SF	0.65	2.50	184.28
74. Remove Emergency lighting - battery - Commercial	1.00 EA	19.05	0.00	19.05
75. (Install) Emergency lighting - battery - Commercial	1.00 EA	0.00	76.86	76.86
76. Mask and prep for paint - plastic, paper, tape (per LF)	224.60 LF	0.00	1.54	345.88
77. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	2,252.11 SF	0.00	1.73	3,896.15
78. Paint door or window opening - 2 coats (per side)	10.00 EA	0.00	34.81	348.10
79. Paint door slab only - 2 coats (per side)	10.00 EA	0.00	40.71	407.10
80. Paint chair rail - two coats	224.60 LF	0.00	1.63	366.10
81. Paint baseboard - two coats	224.60 LF	0.00	1.63	366.10
82. Clean floor, strip & wax	490.33 SF	0.00	0.82	402.07

CORALR-04-15-01 3/26/2018 Page: 10

6,987.57

Apartment G



Back Bedroom	Height: 8'
490.67 SF Walls	184.45 SF Ceiling

675.12 SF Walls & Ceiling
20.49 SY Flooring
61.33 LF Ceil. Perimeter

Door

Subroom: Closet (1)

128.32 SF Walls
12.04 SF Ceiling
140.36 SF Walls & Ceiling
12.04 SF Floor
1.34 SY Flooring
16.04 LF Floor Perimeter

16.04 LF Ceil. Perimeter

2' 6" X 6' 8"

2' 6" X 6' 8"

Opens into BACK_BEDROOM

Opens into MAIN ROOM

Height: 8'


2' 6" X 6' 8" **Opens into BACK BEDROOM** Door DESCRIPTION **QNTY REMOVE REPLACE TOTAL** 0.00 49.25 83. Content Manipulation charge - per hour 2.50 HR 123.13 84. R&R 5/8" drywall - hung, taped, 139.00 SF 0.63 2.86 485.11 floated, ready for paint 85. R&R Baseboard - 3 1/4" 11.58 LF 0.69 3.52 48.75 86. R&R Metal studding, 6" wide, 16" OC, 92.67 SF 0.65 2.50 291.92 25 gauge 87. Window drapery - hardware - Detach & 1.00 EA 0.00 41.11 41.11 88. Mask and prep for paint - plastic, paper, 0.00 1.54 119.15 77.37 LF tape (per LF) 89. Seal/prime then paint the walls and 815.48 SF 0.00 1.42 1,157.98 ceiling twice (3 coats) 90. Paint door or window opening - 2 coats 0.00 3.00 EA 34.81 104.43 (per side) 91. Paint door slab only - 2 coats (per side) 0.00 40.71 122.13 3.00 EA 92. Paint baseboard - two coats 77.37 LF 0.00 1.63 126.11 93. Clean floor, strip & wax 196.49 SF 0.00 0.82 161.12


Totals: Back Bedroom 2,780.94

Total: Apartment G 2,780.94

Total: Third Floor 13,073.84

Fourth Floor





Commercial

CONTINUED - Stair A

104. Seal & paint stair tread - per side - per 60.00 LF 0.00 5.99 33 LF 105. Seal & paint stair riser - per side - per 70.00 LF 0.00 4.00 23 LF 25 25 25 25 25 25 25	DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
LF 105. Seal & paint stair riser - per side - per LF 106. Mask and prep for paint - plastic, paper, tape (per LF) 70.00 LF 0.00 4.00 25. 26.86 LF 0.00 1.54	103. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
LF 106. Mask and prep for paint - plastic, paper, tape (per LF) 26.86 LF 0.00 1.54	1 1	60.00 LF	0.00	5.99	359.40
paper, tape (per LF)	1 1	70.00 LF	0.00	4.00	280.00
Includes risers and treads for top and bottom side of each flight		26.86 LF	0.00	1.54	41.36
	Includes risers and treads for top and bottom side	of each flight			
107. Paint concrete the floor 43.67 SF 0.00 1.01	107. Paint concrete the floor	43.67 SF	0.00	1.01	44.11

Totals: Stair A 1,790.02

Hallway				Height: 8'
	1,761.78 SF Walls		490.33 SF Ceiling	
Signal (1) front Sedraon 7, 1	2,252.11 SF Walls & Ceiling		490.33 SF Floor	
Sair A Sair Sair Sair Sair Sair Sair Sair Sair	54.48 SY Flooring		224.60 LF Floor Peri	meter
Section of Sales of Sales	224.60 LF Ceil. Perimeter			
The same of the sa				
Door	2' 6" X 6' 8"	Opens into	STAIR_A_HALL	
Door	2' 6" X 6' 8"	Opens into	MAIN_ROOM	
Door	2' 6" X 6' 8"	Opens into	STAIR_B	
Door	2' 6" X 6' 8"	Opens into	APT_F	
Door	2' 6" X 6' 8"	Opens into	APT_E	
Door	2' 6" X 6' 8"	Opens into	APT_D	
Door	2' 6" X 6' 8"	Opens into	APT_C	
Door	2' 6" X 6' 8"	Opens into	APT_B	
Door	2' 6" X 6' 8"	Opens into	APT_A	
Window	7' 3" X 4' 10"	Opens into	Exterior	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
108. R&R 5/8" drywall - hung, taped, floated, ready for paint	126.00 SF	0.63	2.86	439.74
109. R&R Chair rail - 2 1/2"	16.50 LF	0.63	3.41	66.67
110. R&R Baseboard - 3 1/4"	16.50 LF	0.69	3.52	69.47
111. R&R Metal studding, 6" wide, 16" OC, 25 gauge	58.50 SF	0.65	2.50	184.28
112. Remove Emergency lighting - battery -	1.00 EA	19.05	0.00	19.05

CONTINUED - Hallway

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
113. (Install) Emergency lighting - battery - Commercial	1.00 EA	0.00	76.86	76.86
114. Mask and prep for paint - plastic, paper, tape (per LF)	224.60 LF	0.00	1.54	345.88
115. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	2,252.11 SF	0.00	1.73	3,896.15
116. Paint door or window opening - 2 coats (per side)	10.00 EA	0.00	34.81	348.10
117. Paint door slab only - 2 coats (per side)	10.00 EA	0.00	40.71	407.10
118. Paint chair rail - two coats	224.60 LF	0.00	1.63	366.10
119. Paint baseboard - two coats	224.60 LF	0.00	1.63	366.10
120. Clean floor, strip & wax	490.33 SF	0.00	0.82	402.07
Totals: Hallway				6,987.57

Apartment G


	14' 6"	— 		Back F
-12' T"	T ලි Back Bedroom	2 4 T	Middle Bed	
	— 12' 8"	9	F	
	12' 4" - 5 Stair A	10"	الله	
Door			Г	

Back Bedroom	Height: 8'
490.67 SF Walls	184.45 SF Ceiling
675.12 SF Walls & Ceiling	184.45 SF Floor
20.49 SY Flooring	61.33 LF Floor Perimeter

61.33 LF Ceil. Perimeter

2' 6" X 6' 8"

Opens into MAIN_ROOM



Subroom:	Closet (1)	Height: 8

128.32 SF Walls12.04 SF Ceiling140.36 SF Walls & Ceiling12.04 SF Floor1.34 SY Flooring16.04 LF Floor Perimeter

16.04 LF Ceil. Perimeter


Door	2' 6" X 6' 8"	Opens into BACK_BEDROOM
Door	2' 6" X 6' 8"	Opens into BACK_BEDROOM

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
121. Content Manipulation charge - per hour	2.50 HR	0.00	49.25	123.13
122. R&R 5/8" drywall - hung, taped, floated, ready for paint	139.00 SF	0.63	2.86	485.11
CORALR-04-15-01			3/26/2018	Page: 14

CONTINUED - Back Bedroom

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
123. R&R Baseboard - 3 1/4"	11.58 LF	0.69	3.52	48.75
124. R&R Metal studding, 6" wide, 16" OC, 25 gauge	92.67 SF	0.65	2.50	291.92
125. Window drapery - hardware - Detach & reset	1.00 EA	0.00	41.11	41.11
126. Mask and prep for paint - plastic, paper, tape (per LF)	77.37 LF	0.00	1.54	119.15
127. Seal/prime then paint the walls and ceiling twice (3 coats)	815.48 SF	0.00	1.42	1,157.98
128. Paint door or window opening - 2 coats (per side)	3.00 EA	0.00	34.81	104.43
129. Paint door slab only - 2 coats (per side)	3.00 EA	0.00	40.71	122.13
130. Paint baseboard - two coats	77.37 LF	0.00	1.63	126.11
131. Clean floor, strip & wax	196.49 SF	0.00	0.82	161.12
Totals: Back Bedroom				2,780.94
Total: Apartment G				2,780.94
Tour. Apartment O				2,700.94
Total: Fourth Floor				13,073.84

Fifth Floor




Door	2' 6" X 6' 8"	Opens into HALLWAY			
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
132. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46	
133. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21	
134. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81	
135. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71	


CONTINUED - Stair A Hall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Totals: Stair A Hall				682.19

Stair A			1	Uoiaht: 12! 6"
7' 11" Stair A Stair A 7' 7" 5 Stair A A Hall 7' 7"	289.70 SF Walls 333.36 SF Walls & Ceiling 4.85 SY Flooring 26.86 LF Ceil. Perimeter		43.67 SF Ceiling 43.67 SF Floor 21.11 LF Floor Peri	Height: 12' 6"
 Missing Wall	5' 9" X 12' 6"	Opens into	STAIR_A_HALL	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
136. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
137. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
138. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
139. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
140. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
141. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom	side of each flight			
142. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A				1,790.02
Total: Fifth Floor				2,472.21

Sixth Floor






DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
147. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
148. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
149. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
150. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
151. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
152. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side	of each flight			
153. Paint concrete the floor ORALR-04-15-01	43.67 SF	0.00	1.01 3/26/2018	44.11 Page: 17

CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Totals: Stair A				1,790.02
Total: Sixth Floor				2,472.21
	Seventh Floor			
Stair A Hall				Height: 8'
in State Control of the State o	252.49 SF Walls		64.97 SF Ceiling	
4 820 V MM	317.46 SF Walls & Ceiling		64.97 SF Floor	
in the second se	7.22 SY Flooring		31.56 LF Floor Per	imeter
	37.31 LF Ceil. Perimeter			
 Missing Wall	5' 9" X 8'	Opens into	o STAIR_A	
Door	2' 6" X 6' 8"	Opens into	o HALLWAY	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
154. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
155. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
156. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
157. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71
Totals: Stair A Hall				682.19




CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
159. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
160. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
161. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
162. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
163. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side of	of each flight			
164. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A				1,790.02

Total: Seventh Floor 2,472.21

Basement



Stairs to Basement Height: 10'

482.49 SF Walls73.14 SF Ceiling555.63 SF Walls & Ceiling73.14 SF Floor8.13 SY Flooring48.08 LF Floor Perimeter

51.46 LF Ceil. Perimeter

Missing Wall 2' 6" X 10' Opens into Exterior



Subroom: Entry Hall (1) Height: 9' 6"

158.76 SF Walls22.52 SF Ceiling181.28 SF Walls & Ceiling22.52 SF Floor2.50 SY Flooring16.71 LF Floor Perimeter

20.09 LF Ceil. Perimeter

Missing Wall

3' 4 9/16" X 9' 6"

Opens into STAIRS_TO_BA

2' 6" X 6' 8"


Opens into Exterior

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
165. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	736.91 SF	0.00	1.73	1,274.85
166. Paint stair stringer - one side	57.33 LF	0.00	4.25	243.65
167. Paint balustrade - two coats CORALR-04-15-01	12.33 LF	0.00	31.11 3/26/2018	383.59 Page: 19

CONTINUED - Stairs to Basement

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
168. Paint handrail - wall mounted	14.33 LF	0.00	1.26	18.06
169. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
170. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
171. Mask and prep for paint - plastic, paper, tape (per LF)	71.55 LF	0.00	1.54	110.19
Totals: Stairs to Basement				2,669.74
Total: Basement				2,669.74

Eighth Floor



├── 7' 11" — Stair A			I	Height: 12' 6"
7' 7" 5	289.70 SF Walls		43.67 SF Ceiling	
Stair A 50	333.36 SF Walls & Ceiling		43.67 SF Floor	
7' 9" -	4.85 SY Flooring		21.11 LF Floor Peri	meter
A Hall 7" 7" ——	26.86 LF Ceil. Perimeter			
 Missing Wall	5' 9" X 12' 6"	Opens into	STAIR_A_HALL	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
176. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
177. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
178. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
179. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
180. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
181. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom s	ide of each flight			
182. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A Total: Eighth Floor				2,472.21
	Ninth Floor			
C. A. H. U.				
Stair A Hall				Height: 8'
Stair A Hall	252.49 SF Walls		64.97 SF Ceiling	Height: 8'
55 500	252.49 SF Walls 317.46 SF Walls & Ceiling		64.97 SF Ceiling 64.97 SF Floor	Height: 8'
17 23 A Mail 1	317.46 SF Walls & Ceiling		64.97 SF Ceiling 64.97 SF Floor 31.56 LF Floor Peri	J
55 8314			64.97 SF Floor	<u> </u>
STANDARD BENDERS.	317.46 SF Walls & Ceiling 7.22 SY Flooring	Opens into	64.97 SF Floor	
Missing Wall	317.46 SF Walls & Ceiling 7.22 SY Flooring 37.31 LF Ceil. Perimeter	=	64.97 SF Floor 31.56 LF Floor Peri	
Missing Wall Door	317.46 SF Walls & Ceiling 7.22 SY Flooring 37.31 LF Ceil. Perimeter 5' 9" X 8'	=	64.97 SF Floor 31.56 LF Floor Peri	
Missing Wall Door DESCRIPTION 183. Mask and prep for paint - plastic,	317.46 SF Walls & Ceiling 7.22 SY Flooring 37.31 LF Ceil. Perimeter 5' 9" X 8' 2' 6" X 6' 8"	Opens into	64.97 SF Floor 31.56 LF Floor Peri	meter
5 35 AND 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	317.46 SF Walls & Ceiling 7.22 SY Flooring 37.31 LF Ceil. Perimeter 5' 9" X 8' 2' 6" X 6' 8" QNTY	Opens into	64.97 SF Floor 31.56 LF Floor Peri	meter

CONTINUED - Stair A Hall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
185. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
186. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71
Totals: Stair A Hall				682.19

Stair A Height: 12' 6"

289.70 SF Walls 333.36 SF Walls & Ceiling 4.85 SY Flooring 26.86 LF Ceil. Perimeter 43.67 SF Ceiling 43.67 SF Floor

21.11 LF Floor Perimeter


Missing Wall 5' 9" X 12' 6" Opens into STAIR_A_HALL

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
187. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
188. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
189. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
190. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
191. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
192. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side	e of each flight			
193. Paint concrete the floor	43.67 SF	0.00	1.01	44.11

Totals: Stair A 1,790.02

Total: Ninth Floor 2,472.21

Tenth Floor



Stair A Hall Height: 8'


> 252.49 SF Walls 64.97 SF Ceiling 317.46 SF Walls & Ceiling 64.97 SF Floor 7.22 SY Flooring 31.56 LF Floor Perimeter

37.31 LF Ceil. Perimeter

5' 9" X 8' Opens into STAIR_A Door 2' 6" X 6' 8" **Opens into HALLWAY**

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
194. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
195. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
196. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
197. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71

Totals: Stair A Hall 682.19



Stair A Height: 12' 6"

> 43.67 SF Ceiling 289.70 SF Walls 333.36 SF Walls & Ceiling 43.67 SF Floor 21.11 LF Floor Perimeter 4.85 SY Flooring


26.86 LF Ceil. Perimeter

Missing Wall 5' 9" X 12' 6" Opens into STAIR_A_HALL

_		_		
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
198. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
199. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
200. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
201. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
202. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
203. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side	of each flight			
204. Paint concrete the floor ORALR-04-15-01	43.67 SF	0.00	1.01 3/26/2018	44.11 Page: 2

CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Totals: Stair A				1,790.02
Total: Tenth Floor				2,472.21
	Eleventh Floor			
Stair A Hall				Height: 8'
in State 1	252.49 SF Walls		64.97 SF Ceiling	
	317.46 SF Walls & Ceiling		64.97 SF Floor	
T I I I I I I I I I I I I I I I I I I I	7.22 SY Flooring		31.56 LF Floor Per	imeter
	37.31 LF Ceil. Perimeter			
Missing Wall	5' 9" X 8'	Opens into	o STAIR_A	
Door	2' 6" X 6' 8"	Opens into	O HALLWAY	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
205. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
206. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
207. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
208. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71
Totals: Stair A Hall				682.19




CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
210. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
211. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
212. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
213. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
214. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side of	of each flight			
215. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A				1,790.02

Total: Eleventh Floor 2,472.21

Twelfth Floor



Stair A Hall

252.49 SF Walls
317.46 SF Walls & Ceiling
7.22 SY Flooring

44.97 SF Ceiling
64.97 SF Floor
31.56 LF Floor Perimeter

37.31 LF Ceil. Perimeter

Missing Wall 5' 9" X 8'
Door 2' 6" X 6' 8"

Opens into STAIR_A
Opens into HALLWAY

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
216. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
217. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
218. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
219. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71

Totals: Stair A Hall 682.19

7' 7" 50 5tair A 50 50 7' 9"	200 70 CE W 11			Height: 12' 6'
io 1	289.70 SF Walls		43.67 SF Ceiling	
	333.36 SF Walls & Ceiling		43.67 SF Floor	
<u> </u>	4.85 SY Flooring		21.11 LF Floor Peri	meter
A Hall 7' 7" ———	26.86 LF Ceil. Perimeter			
Missing Wall	5' 9" X 12' 6"	Opens into	STAIR_A_HALL	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
220. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
221. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
222. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
223. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
224. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
225. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
ncludes risers and treads for top and bottom s	side of each flight			
226. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Total: Twelfth Floor				2,472.21
	Thirteenth Floor			
Stair A Hall				Height: 8
in Stair A	252.49 SF Walls		64.97 SF Ceiling	
	317.46 SF Walls & Ceiling		64.97 SF Floor	
=+ sestr A Hall 1	7.22 SY Flooring		31.56 LF Floor Peri	
\$\frac{1}{27} \tag{256 A Major \frac{1}{27} \tag{256 C Major \frac{1}{27} 256 C Major			31.30 LT 11001 1 CH	meter
	37.31 LF Ceil. Perimeter		51.30 El 11001 l'ell	meter
	_	Opens into	o STAIR_A	meter
5- 1- Elevators ±	37.31 LF Ceil. Perimeter	_		meter
Missing Wall	37.31 LF Ceil. Perimeter 5' 9" X 8'	_	o STAIR_A	TOTAL
Missing Wall Door DESCRIPTION 227. Mask and prep for paint - plastic,	37.31 LF Ceil. Perimeter 5' 9" X 8' 2' 6" X 6' 8"	Opens into	o STAIR_A o HALLWAY	
Missing Wall	37.31 LF Ceil. Perimeter 5' 9" X 8' 2' 6" X 6' 8" QNTY	Opens into	D STAIR_A D HALLWAY REPLACE	TOTAL

CONTINUED - Stair A Hall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
229. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
230. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71
Totals: Stair A Hall				682.19

Stair A Height: 12' 6"

289.70 SF Walls 333.36 SF Walls & Ceiling 4.85 SY Flooring 26.86 LF Ceil. Perimeter 43.67 SF Ceiling
43.67 SF Floor

21.11 LF Floor Perimeter


Missing Wall 5' 9" X 12' 6"	Opens into STAIR_A_HALL
-----------------------------	-------------------------


DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
231. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
232. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
233. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
234. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
235. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
236. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side	of each flight			
237. Paint concrete the floor	43.67 SF	0.00	1.01	44.11

Totals: Stair A 1,790.02

Total: Thirteenth Floor 2,472.21

Fourteenth Floor






5' 9" X 12' 6"	Opens into STAIR_A_HALL		
QNTY	REMOVE	REPLACE	TOTAL
333.36 SF	0.00	1.73	576.71
24.67 LF	0.00	4.25	104.85
12.33 LF	0.00	31.11	383.59
60.00 LF	0.00	5.99	359.40
70.00 LF	0.00	4.00	280.00
26.86 LF	0.00	1.54	41.36
de of each flight			
43.67 SF	0.00	1.01 3/26/2018	44.11 Page: 2
	QNTY 333.36 SF 24.67 LF 12.33 LF 60.00 LF 70.00 LF 26.86 LF de of each flight	QNTY REMOVE 333.36 SF 0.00 24.67 LF 0.00 12.33 LF 0.00 60.00 LF 0.00 70.00 LF 0.00 26.86 LF 0.00 de of each flight	QNTY REMOVE REPLACE 333.36 SF 0.00 1.73 24.67 LF 0.00 4.25 12.33 LF 0.00 31.11 60.00 LF 0.00 5.99 70.00 LF 0.00 4.00 26.86 LF 0.00 1.54 de of each flight 43.67 SF 0.00 1.01

Totals: Stair A Hall

CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Totals: Stair A				1,790.02
Total: Fourteenth Floor				2,472.21
	Fifteenth Floor			
Stair A Hall				Height: 8'
is sair A	252.49 SF Walls		64.97 SF Ceiling	
5 <u>85</u> 7 A Hall	317.46 SF Walls & Ceiling		64.97 SF Floor	
- 1 1 1 1 1 1 1 1 1	7.22 SY Flooring		31.56 LF Floor Per	imeter
	37.31 LF Ceil. Perimeter			
 Missing Wall	5' 9" X 8'	Opens into	STAIR_A	
Door	2' 6" X 6' 8"	Opens into	HALLWAY	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
249. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46
250. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21
251. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81
252. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71




682.19

CONTINUED - Stair A

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
254. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
255. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
256. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
257. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
258. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side of	of each flight			
259. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A				1,790.02

Total: Fifteenth Floor 2,472.21

Sixteenth Floor



64.97 SF Ceiling 64.97 SF Floor 31.56 LF Floor Perimeter

Height: 8'

Door	2' 6" X 6' 8"	Opens into HALLWAY			
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
260. Mask and prep for paint - plastic, paper, tape (per LF)	37.31 LF	0.00	1.54	57.46	
261. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	317.46 SF	0.00	1.73	549.21	
262. Paint door or window opening - 2 coats (per side)	1.00 EA	0.00	34.81	34.81	
263. Paint door slab only - 2 coats (per side)	1.00 EA	0.00	40.71	40.71	
Totals: Stair A Hall				682.19	

F 7-11"
7' 7"
Stair A O
7' 9"
A Hall 7' 7" ———
Missing Wall

Stair A Height: 12' 6"

289.70 SF Walls 333.36 SF Walls & Ceiling

4.85 SY Flooring

26.86 LF Ceil. Perimeter

43.67 SF Ceiling 43.67 SF Floor

21.11 LF Floor Perimeter

Missing Wall 5' 9" X 12' 6"	Opens into STAIR_A_HALL
-----------------------------	-------------------------

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
264. Seal/prime then paint the walls and ceiling twice (3 coats) - 2 colors	333.36 SF	0.00	1.73	576.71
265. Paint stair stringer - one side	24.67 LF	0.00	4.25	104.85
266. Paint balustrade - two coats	12.33 LF	0.00	31.11	383.59
267. Seal & paint stair tread - per side - per LF	60.00 LF	0.00	5.99	359.40
268. Seal & paint stair riser - per side - per LF	70.00 LF	0.00	4.00	280.00
269. Mask and prep for paint - plastic, paper, tape (per LF)	26.86 LF	0.00	1.54	41.36
Includes risers and treads for top and bottom side of	of each flight			
270. Paint concrete the floor	43.67 SF	0.00	1.01	44.11
Totals: Stair A				1,790.02

Total: Sixteenth Floor 2,472.21

Electrical

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
322. Electrician - per hour	1,350.00 HR	0.00	120.10	162,135.00

Electrician per hour to include: (as per bid from Demand Electric - Brooklyn, New York)

- 1) all necessary labor required to remove existing BX wiring, devices and conduit from the basement to the 5th floor to allow for necessary demo procedures
- 2) installation of all temporary conduits, BX wiring, 200 AMP electric panels per floor, fire alarm pull boxes, hi=hats, florescent lighting fixtures throughout stairwell, door lock set-ups, cameras, telephones, speaker strobes, exit signs, outlets and switches
- 3) after all necessary repairs have been completed removal of all temporary conduits, BX wiring, 200 AMP electric panels per floor, fire alarm pull boxes, hi=hats, florescent lighting fixtures throughout stairwell, cameras, telephones, speaker strobes, outlets and switches will be executed to allow for replacement of all original devices, conduits and BX wiring to bring building back to pre-existing condition
- 4) re-installation of all wiring, conduits and devices that were removed at the beginning of the project

323. ELECTRICAL - materials 1.00 TL 0.00 52,000.00 52,000.00

CONTINUED - Electrical

DESCRIPTION ONTY REMOVE REPLACE TOTAL

Materials to include: (as per bid from Demand Electric - Brooklyn, New York)

1) fire alarm pull boxes w/ 4" conduit, door lock set ups for card readers, exit signs, speaker strobes, pull stations, hi=hats, florescent light fixtures, cameras, telephones, BX wiring, Cat 5E wiring, fire alarm wiring, temp wiring and fixtures for stairwell, all necessary conduits for wiring w/ associated hanging devices, 200 AMP electrical panels, junction boxes, outlets, switches and misc. materials

Totals: Electrical 214,135.00

Exterior/General

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
282. Detach & Reset Neon sign - large -	1.00 TL	0.00	0.00	13,500.00
High grade - Duane Reade sign				

Please Note, the removal of the large wall mounted exterior sign will include the following:

- 1) scissor lift to remove and reset the sign
- 2) capping off of existing electrical feeds leading to the sign
- 3) off-site storage for up to 12 months
- 4) resetting and re-energizing the sign after the necessary structure repairs have been completed

Totals: Exterior/General 13,500.00

Stairway

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
293. Structural steel framing - high rise bldg per ton	24.00 TN	0.00	3,191.84	76,604.16
Supply and install structural steel framing to ac street	ecommodate and suppo	rt installation of exteri	or stairwell leading	down to the
325. Concrete Piles - 24" diameter	60.00 LF	0.00	135.76	8,145.60
Footings for vertical structural steel footing				
326. Insulation - ISO board, 1"	2.50 SQ	0.00	185.58	463.95
327. Flashing, 14" wide - copper	70.00 LF	0.00	10.04	702.80
328. Aluminum termination bar / flashing for membrane roofs	24.00 LF	0.00	2.60	62.40
329. Glass mat gypsum - 1/2" - primed	2.50 SQ	0.00	199.21	498.03
330. Modified bitumen roof - hot mopped	2.50 SQ	0.00	390.60	976.50
331. Remove Additional charge for high roof (2 stories or greater)	2.50 SQ	8.04	0.00	20.10

CONTINUED - Stairway

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
332. Additional charge for high roof (2 stories or greater)	2.50 SQ	0.00	18.63	46.58
294. Concrete pump truck (per hour) - 8 hrs per day x 6 days	48.00 HR	0.00	297.57	14,283.36
296. Concrete slab on grade - 8" - finished in place	1,440.00 SF	0.00	6.71	9,662.40
297. Steel rebar - #10 (1-1/4")	900.00 LF	0.00	5.31	4,779.00
298. Concrete slab reinforcement - #3 (3/8") - grid, 24" ea way	1,440.00 SF	0.00	0.75	1,080.00
316. Temporary Egress Staircase from the 6th floor to the street - as per proposed drawings	1.00 TL	0.00	484,285.71	484,285.71
Please Note - the proposed quote includes fabri staircase upon completion of the project	cation of staircase off-s	ite, installation of the s	taircase and remov	al of the
312. Metal studding, 6" wide, 16" OC, 20 gauge	3,600.00 SF	0.00	2.70	9,720.00
317. Steel door, 3' x 7' - with glass lite	6.00 EA	0.00	1,475.00	8,850.00
318. Residential automatic door operator system	6.00 EA	0.00	1,582.24	9,493.44
319. Wireless/Keyless entry pad for auto door operator system	6.00 EA	0.00	140.01	840.06
Entry door units w/ key less entry and automat	tic door opener per floo	r and for the street lev	el entrance	
313. Sheathing - fiberglass gypsum panel - 5/8"	4,800.00 SF	0.00	1.84	8,832.00
314. 5/8" drywall - hung, taped, floated, ready for paint	6,000.00 SF	0.00	2.86	17,160.00
315. Seal/prime then paint the surface area twice (3 coats)	2,900.00 SF	0.00	1.42	4,118.00
Includes panting of new drywall for all 6 floors				
Totals: Stairway				660,624.09

Demolition

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
292. General Demolition - per hour - front elevation	1,728.00 HR	76.19	0.00	131,656.32

CONTINUED - Demolition

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
General Demolition labor to include: 12 men, 8 h 1) removal of exterior facade wall panels, window purpose of exposing structural support columns a floor decks and wall build outs 2) complete removal of interior walls where wind installed in to new stairwell	units and backing board I-beams to allow	oard per floor directly for installation and ere	ction of the exterior	staircase,
Please Note - the temporary stairwell will start or be taking place to allow for the necessary egress t		elevation (5th floor) w	here the actual dem	olition will
306. General Demolition - per hour - removal of all structural materials and 7,500 PSI concrete wall from adjoining building - 6 floors total	10,560.00 HR	76.19	0.00	804,566.40
General Demolition labor to include: 12 men, 8 h 1) removal of exterior facade wall panels, backing on the south side of the building from the 1st floo I-beams to allow for installation of the copper pan back to its pre-loss condition. All debris will be hand carried through existing s	g board, galvanized w r to the 6th floor for t nel system and necess	all studs, drywall, trim he purpose of exposing ary structural material	structural support is needed to return	columns and the building
Please Note - there are 8 weekend days that were	deducted from a 30 d	ay month		-
321. General Demolition - per hour - front elevation - removal of all temporary structural materials	2,880.00 HR	76.19	0.00	219,427.20
General Demolition labor to include: 12 men, 8 h 1) removal of all temporary building materials to floor			on from the baseme	nt ot the 6th
307. General Demolition Equipment & Materials - electric jack hammers, concrete saw cutting equipment w/ diamond blades, compressors, hoses & PPE per man, per day - per floor	5.00 PF	0.00	9,750.00	48,750.00
Please Note - a repair supplement may be needed project exceeds the proposed amount of time allo		procedures and/or he	avy equipment need	led for this
340. Neg. air fan/Air scrubXLrg (per 24 hr period)-No monit.	300.00 DA	0.00	155.00	46,500.00
Please Note - HEPA equipped air scrubber will b the migration of dust throughout the building. Th procedures				
341. Add for HEPA filter (for neg. air machine/vacuum - Large)	40.00 EA	0.00	247.91	9,916.40
Totals: Demolition				1,260,816.32

CORALR-04-15-01 3/26/2018 Page: 34

Left Elevation

CONTINUED - Left Elevation

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
285. Copper Panel Installer per hour - per hour	4,224.00 HR	0.00	129.19	545,698.56
286. Copper Panel General Laborer - per hour	2,112.00 HR	0.00	49.25	104,016.00
Copper Panel Installer labor per hour to inclu 1) fabrication of exterior grade copper panels soldered seams 2) installation of copper lentil at the 8' height 3) vertical & horizontal soldering of the copper	on site using pneumatic per floor to hold panels i	n place prior to soldering		o allow for
284. (Material Only) Copper panel system for south exterior wall - standing seam 1" - 20 oz - fabricated on site - includes waste	4,500.00 SF	0.00	14.43	64,935.00
305. Premium self adhering SBS asphalt water barrier - Fully adhered system - 90 mil	43.00 SQ	0.00	565.88	24,332.84
287. Provide and install new elastomeric sealant in vertical and horizontal panel joints	4,224.00 LF	0.00	7.50	31,680.00
288. Provide and install metal flashing and counterflashing where needed to correspond with panel placement between levels	240.00 LF	0.00	45.00	10,800.00
300. Lag bolt - 1/2" x " - hex lag screw - zinc plated	1,584.00 EA	0.00	13.95	22,096.80
289. Fire retardant insulation - Spray-on mineral fiber	3,024.00 SF	0.00	1.65	4,989.60
290. Acoustical/fire-safing insulation - 6" mineral wool	3,024.00 SF	0.00	1.51	4,566.24
301. Moisture protection for exterior walls - visqueen - 6 mil	3,024.00 SF	0.00	0.47	1,421.28
302. Metal studding, 6" wide, 16" OC, 20 gauge	3,024.00 SF	0.00	2.70	8,164.80
303. Sheathing - fiberglass gypsum panel - 5/8"	4,500.00 SF	0.00	1.84	8,280.00
304. 5/8" drywall - hung, taped, floated, ready for paint	4,500.00 SF	0.00	2.86	12,870.00
324. Drywall Installer / Finisher - per hour	100.00 HR	0.00	91.44	9,144.00
Drywall labor per hour to include: 1) scrape, tape, spackle and sand affected area	as not being replaced - 20) hours per floor x 5 flooi	rs	
308. Supply, install and remove temporary stainless steel trash chute from the 6th floor to the basement during necessary repairs	1.00 TL	190,000.00	0.00	190,000.00

CONTINUED - Left Elevation

DESCRIPTION ONTY REMOVE REPLACE TOTAL

Please Note - the proposed costs for the trash chute include:

- 1) removal of the existing chute from the 5th floor to the basement
- 2) fabrication of 2' wide stainless steel chute to be attached the exiting chute on a 45 degree angle at the 5th floor and street level
- 3) fabrication of trash chute doors on each floor for the purpose of access for all students and building staff
- 4) removal of temporary chute after necessary repairs have been completed
- 5) re-installation of existing trash chute and doors back to pre-loss condition

Totals: Left Elevation 1,042,995.12

HVAC

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
291. HVAC - supply, install and remove roof mounted units for the purpose of air conditiong existing areas and proper pressurization of exterior stairwell	1.00 TL	0.00	515,450.00	515,450.00

HVAC bid item to include the following: (as per bid from Nelson Air Device - Maspeth, New York)

- 1) remove, relocate and re-install 6 wall mounted convector units presently in front of the windows from the 2nd floor to the 6th floor
- 2) remove A/C unit front the entry foyer roof and relocate on the roof temporarily while structure repairs are being performed (18 story building). After repairs have been completed the A/C will be re-installed at it present location
- 3) supply and install all necessary ductwork from the buildings roof through the stairwell and in to the reception area for the purpose of positive pressure and heat inside of the new staircase.
- 4) includes the cost of large crane w/ necessary permits and fees that will require that the street be closed down twice between 14th and 15th street on 3rd avenue on approved Saturdays by the NYC Dept of Building to allow installation of roof top units and removal of said units after all necessary repairs have been completed
- 5) attached cost includes the all necessary man hours, supervision, materials and cost HVAC units. (all costs to be determined after final drawings have been approved by NYC Building Dept and subsequent parties involved with this claim)

320. Fire Sprinklers - extend 2" fire sprinklers pipes w/ new heads per floor and return to existing locations after repairs have been completed

6.00 EA

0.00

4,319.56

25,917.36

Includes purging and testing of existing system from the basement to the 6th floor. There will be a total 3 sprinklers per floor that will require rerouting to properly protect existing ares and the new stairwell being installed

Totals: HVAC 541.367.36

Debris Removal

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
280. Live load pick up per CY - includes loading debris into dump truck	960.00 CY	100.00	0.00	96,000.00
CORALR-04-15-01			3/26/2018	Page: 36

CONTINUED - Debris Removal

DESCRIPTION	ONTY	REMOVE	REPLACE	TOTAL
DESCRIFTION	UNII	KEMUVE	REFLACE	IUIAL

Please Note - due to the weight of the 7,500 PSI concrete that is being removed, the CY cost has been changed to reflect the cost of debris removal in Manhattan. The total of amount of debris being removed is subject to change and a repair supplement might be required after a manifest of the debris being removed has been presented

Totals: Debris Removal 96,000.00

Scaffolding

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
271. Scaffolding - provide suspended electric scaffolding & side walk roof	18.00 EA	0.00	27,500.00	495,000.00
Scaffolding system to include:				

1) 23 total material drops, 8 initial set ups and approx. 18 moves to allow for necessary demo, build out and breakdown of entire staircase system

272. Scaffolding - scaffolding insurance, 1.00 TL 0.00 17,500.00 17,500.00 permits and fees

Please Note - scaffolding insurance, permits and fees is generally paid as incurred. The attached cost for these items will be subject to change upon execution of this aforementioned project.

Totals: Scaffolding 512,500.00

Post Construcion Clean Up

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
274. Cleaning - Supervisory/Administrative - per hour	2,080.00 HR	0.00	60.50	125,840.00
273. Cleaning Technician - incl. cleaning agent - per hour	4,160.00 HR	0.00	45.38	188,780.80

Cleaning Technician labor to include: 3 man staff per floor x 5 days - 5 floors total for approx. 52 weeks
1) perform post construction clean up of all affected floors throughout the building during and after necessary demo & structure repairs have been completed. These procedures will be performed on a weekly basis due to the building being occupied by students/residents/staff

Totals: Post Construcion Clean Up 314,620.80

Off Site Storage

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL

CONTINUED - Off Site Storage

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
309. Packaging, Handling, Storage - off site	48.00 UN	0.00	365.00	17,520.00
storage				

Off Site Storage to include:

1) off site storage for the following items to be re-installed after necessary structure repairs have been completed (affected windows, doors, heating units, garbage chute doors and A/C unit on lower roof above entry way) for 1 year. The terms of the storage will be adjusted as per the length of the project. Includes packing out and protection of said items prior to being moved off site

2) 4 large units x 12 months (actual storage duration to be determined)

335. Moving van (24' - 27') and equipment - per day	4.00 EA	0.00	190.29	761.16
337. Contents Evaluation and/or Supervisor/Admin - per hour	16.00 HR	0.00	60.50	968.00
336. Inventory, Packing, Boxing, and Moving charge - per hour	112.00 HR	0.00	49.25	5,516.00

8 men, $8 \text{ hrs each } x \text{ 2 days for moving the structural items to an off site storage location for the duration of the project and returning said items to the building to be re-installed$

Totals: Off Site Storage 24,765.16

Site Work/Excavation

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
333. CONCRETE & ASPHALT	1.00 TL	0.00	125,000.00	125,000.00

Site work/Excavation on 3rd Avenue to include the following items:

- 1) Permits/lane closures for the sidewalk includes 5' long plastic jersey barricades, metal decking road plates (2 month rental period) & delivery charge for metal road plates \$ 12,500
- 2) Street work removals includes chopping/saw cutting concrete sidewalk flags and pavement and necessary equipment/man power needed to perform necessary task \$ 17,500
- 3) Excavation underground utility survey, excavation and necessary equipment/man power needed to perform necessary task \$ 65,000
- 4) Backfill control fill and necessary equipment/man power needed to perform necessary task \$ 25,000
- 5) Permits and associated Fees will be needed for professional engineering drawings for sheeting, cylinder compression testing, 2 slump tests, 3/4" stone gravel test and a concrete compaction test (all costs to be determined) \$5,000

Totals: Site Work/Excavation 125,000.00

Concrete Foundation

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
334. CONCRETE & ASPHALT	1.00 EA	0.00	28,500.00	28,500.00

CONTINUED - Concrete Foundation

DESCRIPTION ONTY REMOVE REPLACE TOTAL

Concrete Foundation on 3rd Avenue to include the following items:

- 1) Spread concrete footings includes #5 rebars1' O.C. each way w/ epoxy coat, form stripping, allowance for removal of forms, allowance for short load fee and necessary equipment/man power needed to perform necessary task \$8,000
- 2) Sidewalk Restoration includes gravel fill, 4000 PSI concrete, welded wire fabric, allowance for short load fee & broom finish and necessary equipment/man power needed to perform necessary task \$7,500
- 3) Tie beams includes tyeing in foundation so it is rigid, rebar w/ ties 12" O.C., form stripping, allowance for removal of forms and necessary equipment/man power needed to perform necessary task \$12,000
- 4) Permits and associated Fees will be needed for a cylinder compression testing, 2 slump tests and 3/4" stone gravel test (all costs to be determined) \$1,000

Totals: Concrete Foundation 28,500.00

General Conditions

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
277. Commercial Supervision / Project Management - per hour	4,160.00 HR	0.00	85.01	353,641.60
2 Supervisors, 8 hrs. per day x 5 days x 52 weeks				
342. Safety Monitor - per hour	2,080.00 HR	0.00	125.00	260,000.00

OSHA regulations and training specify that a safety monitor is a worker whose SOLE DUTY is to protect up to 8 other workers. Safety calculations are based on labor hours provided by Xactimate, in compliance with OSHA 1926.502 (h) (1).

278. General Laborer - per hour 2,080.00 HR 0.00 49.25 102,440.00

General Labor to include:

- 1) protection of common hallways, stairwells and entry foyer during the structure repair procedures
- 2) additional labor required to load and unload structure materials in a residential area with limited parking
- 3) labor associated with hand carrying necessary structural materials through narrow stairwells to designated floors where work is being performed
- 4) daily site clean up of work areas

2 men, 4 hrs. per day x 5 day work week for 52 weeks

279. Taxes, insurance, permits & fees (Bid 1.00 TL 0.00 72,000.00 72,000.00 item)

Please Note - all necessary permits and fees are to be paid as incurred (this cost excludes the price of an expediter) Attached is the approx. costs for the permits and fees that will be required by the NYC Building Dept.

Totals: General Conditions 788,081.60

Line Item Totals: CORALR-04-15-01 5,704,488.71

Grand Total Areas:

193,684. 34	SF Walls	111,295. 33	SF Ceiling	304,979. 67	SF Walls and Ceiling
111,296. 16	SF Floor	12,366.24	SY Flooring	23,767.95	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	23,965.04	LF Ceil. Perimeter
111,296. 16	Floor Area	116,035. 98	Total Area	194,198. 68	Interior Wall Area
41,115.42	Exterior Wall Area	5,594.71	Exterior Perimeter of Walls		
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length

Summary

Line Item Total			5,704,488.71
Overhead	@	10.0%	561,499.17
Profit	@	10.0%	561,499.17
Total Tax(Rep-Maint)	@	8.875%	599,529.11
Replacement Cost Value			\$7,427,016.16
Net Claim			\$7,427,016.16

Ken Wilson

Recap by Room

Estimate:	CORALR-04-15-01

Stair A Hall 2,729,42 0,05% Stair A 1,790,02 0,03% Hallway 6,987,57 0,12% Area Subtotal: Second Floor 11,507,01 0,20% Area: Third Floor 11,507,01 0,20% Area: Third Floor 1,515,31 0,03% Stair A 1,790,02 0,03% Hallway 6,987,57 0,12% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Apartment G 2,780,94 0,05% Area Subtotal: Third Floor 13,073,84 0,23% Area: Fourth Floor 13,073,84 0,23% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Third Floor 13,073,84 0,23% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Apartment G 2,780,94 0,05% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Fifth Floor 13,073,84 0,23% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Subtotal: Fifth Floor 13,073,84 0,23% Area: Fifth Floor 13,073,84 0,23% Area: Subtotal: Fifth Floor 13,073,84 0,23% Area: Floor 13,073,84 0,23%	Area: Main Level		
Stairwell A 1,805.61 0.03%	· ·		
Area Subtotal: Main Level 11,592.31 0.20% Area: Second Floor Stair A Hall 2,729.42 0.05% Stair A Hallway 6,987.57 0.12% Area Subtotal: Second Floor 11,507.01 0.20% Area: Third Floor Stair A Hall 1,515.31 0.03% Stair A 1,790.02 0.03% Hallway 6,987.57 0.12% Area: Apartment G Back Bedroom 2,780.94 0.05% Area Subtotal: Apartment G Stair A Hall 1,515.31 0.03% Area: Fourth Floor 13,073.84 0.23% Area: Fourth Floor Stair A Hall 1,515.31 0.03% Stair A 1,790.02 0.03% Hallway 6,987.57 0.12% Area: Subtotal: Third Floor 13,073.84 0.23% Area: Fourth Floor Stair A Hall 1,515.31 0.03% Stair A 1,790.02 0.03% Hallway 6,987.57 0.12% Area: Apartment G 2,780.94 0.05% Area: Apartment G 2,780.94 0.05% Area: Apartment G 2,780.94 0.05% Area: Subtotal: Apartment G 2,780.94 0.05% Area: Subtotal: Fourth Floor 13,073.84 0.23% Area: Subtotal: Fourth Floor 13,073.84 0.23% Area: Fifth Floor 2,780.94 0.05% Area Subtotal: Fourth Floor 13,073.84 0.23% Area Subtotal: Fourth Floor 2,780.94 0.05% Area Subtotal: Fourth Floor 2,780.94 0.05% Area Subtotal: Fourth Floor 3,000.00% Area Subtotal: Fourth Floor 2,780.94 0.05% Area Subtotal: Fifth Floor 2,472.21 0.04%			
Area: Second Floor Stair A Hall Stair A Hallway Area Subtotal: Second Floor Area Subtotal: Second Floor Area: Third Floor Stair A Hall Stair A 1,590.02 Area: Third Floor Stair A Hall Stair A 1,790.02 Area: Third Floor Stair A Hall Stair A 1,790.02 0,03% Hallway 1,515.31 0,03% Stair A 1,790.02 0,03% Area: Apartment G Back Bedroom 2,780.94 0,05% Area Subtotal: Third Floor Stair A Hall 1,515.31 0,03% Stair A 1,073.84 0,23% Area: Fourth Floor Stair A Hall 1,515.31 0,03% Stair A 1,790.02 0,03% Hallway 6,987.57 0,12% Area: Apartment G Back Bedroom 2,780.94 0,05% Area: Apartment G Stair A 1,790.02 0,03% Area: Apartment G Back Bedroom 2,780.94 0,05% Area: Fifth Floor Stair A Hall 1,073.84 0,23% Area: Fifth Floor Stair A Hall 1,073.84 0,23% Area: Fifth Floor Stair A Hall 1,790.02 0,03% Area Subtotal: Fourth Floor Stair A Hall 1,790.02 0,03% Area Subtotal: Fifth Floor	Stairwell A	1,805.61	0.03%
Stair A Hall 2,729,42 0,05% Stair A 1,790,02 0,03% Hallway 6,987,57 0,12% Area Subtotal: Second Floor 11,507,01 0,20% Area: Third Floor 11,507,01 0,20% Area: Third Floor 1,515,31 0,03% Stair A 1,790,02 0,03% Hallway 6,987,57 0,12% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Apartment G 2,780,94 0,05% Area Subtotal: Third Floor 13,073,84 0,23% Area: Fourth Floor 13,073,84 0,23% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Third Floor 13,073,84 0,23% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Apartment G 2,780,94 0,05% Area: Subtotal: Apartment G 2,780,94 0,05% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Fifth Floor 13,073,84 0,23% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Subtotal: Fourth Floor 13,073,84 0,23% Area: Subtotal: Fifth Floor 13,073,84 0,23% Area: Fifth Floor 13,073,84 0,23% Area: Subtotal: Fifth Floor 13,073,84 0,23% Area: Floor 13,073,84 0,23%	Area Subtotal: Main Level	11,592.31	0.20%
Stair A	Area: Second Floor		
Hallway 6,987,57 0,12% Area Subtotal: Second Floor 11,507,01 0,20% Area: Third Floor	Stair A Hall	2,729.42	0.05%
Area Subtotal: Second Floor Area: Third Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Stair A Hall Stair A Area Subtotal: Third Floor Stair A Hall Apartment G Back Bedroom Area Subtotal: Third Floor Area: Fourth Floor Stair A Hall Stair A Area: Apartment G Back Bedroom Area: Fourth Floor Stair A Hall Stair A Area: Apartment G Back Bedroom Area: Apartment G Back Bedroom Area: Fourth Floor Stair A Hall Stair A Area: Apartment G Back Bedroom Area: Apartment G Back Bedroom Area: Apartment G Back Bedroom Area: Subtotal: Apartment G Back Bedroom Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Area Subtotal: Fifth Floor Area Subtotal: Fifth Floor	Stair A	1,790.02	0.03%
Area: Third Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Stair A Hall Stair A Area Subtotal: Third Floor Stair A Hall Stair A Area Subtotal: Third Floor Area: Fourth Floor Stair A Hall Stair A Area: Apartment G Back Bedroom 2,780.94 0.05% Area: Fourth Floor Stair A Hall Stair A 1,790.02 0.03% Hallway Area: Apartment G Back Bedroom 2,780.94 Area: Apartment G Back Bedroom 2,780.94 Area: Subtotal: Fourth Floor Area: Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A 1,790.02 0.03% Area: Fifth Floor Stair A Hall Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor Stair A Hall Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor Stair A Hall Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor Stair A Hall Stair A 1,790.02 0.03%	Hallway	6,987.57	0.12%
Stair A Hall 1,515.31 0.03% Stair A 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.05% 1,790.04 0.05% 1,790.04 0.05% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.05% 1,790.02 0.05% 1,790.02 0.05% 1,790.04 1,790.04 1,790.05% 1,790.04 1,790.05% 1,790.04 1,790.05% 1,790.04 1,790.05% 1,790.04 1,790.04 1,790.05% 1,790.04 1,790.05% 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,790.02 1,790.04 1,	Area Subtotal: Second Floor	11,507.01	0.20%
Stair A Hallway 1,790.02 0.03% 6,987.57 0.12%	Area: Third Floor		
Hallway 6,987.57 0,12% Area: Apartment G Back Bedroom 2,780.94 0.05% Area Subtotal: Apartment G 13,073.84 0.23% Area: Fourth Floor 13,073.84 0.23% Area: Fourth Floor 1,790.02 0.03% Area: Apartment G 2,780.94 0.05% Area Subtotal: Apartment G 2,780.94 0.05% Area Subtotal: Fourth Floor 13,073.84 0.23% Area: Fifth Floor 13,073.84 0.23% Area: Fifth Floor 2,472.21 0.04% Area Subtotal: Fifth Floor 2,472.21 0.04%	Stair A Hall	1,515.31	0.03%
Area: Apartment G Back Bedroom Area Subtotal: Apartment G Area Subtotal: Third Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Back Bedroom Area Subtotal: Fourth Floor Stair A Hall Area Subtotal: Fourth Floor Stair A Hall Area Subtotal: Fourth Floor Area: Fifth Floor Stair A Area: Fifth Floor Stair A Area Subtotal: Fourth Floor Stair A Area Subtotal: Fifth Floor	Stair A	1,790.02	0.03%
Back Bedroom 2,780.94 0.05%	Hallway	6,987.57	0.12%
Area Subtotal: Apartment G Area Subtotal: Third Floor Area: Fourth Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Back Bedroom Area Subtotal: Fourth Floor Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fourth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor 2,472.21 0.04%	Area: Apartment G		
Area Subtotal: Third Floor Area: Fourth Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Area Subtotal: Fourth Floor Stair A Hall Area Subtotal: Fourth Floor Area: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor 2,472.21 0.04%	Back Bedroom	2,780.94	0.05%
Area: Fourth Floor Stair A Hall Stair A Hallway Area: Apartment G Back Bedroom Area Subtotal: Apartment G Area Subtotal: Fourth Floor Stair A Hall Area Subtotal: Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Area Subtotal: Apartment G	2,780.94	0.05%
Stair A Hall 1,515.31 0.03% Stair A 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.02% 1,780.94 0.05% 1,780.94 0.05% 1,780.94 0.05% 1,780.94 0.05% 1,780.94 0.23% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.03% 1,790.02 0.04% 1,790	Area Subtotal: Third Floor	13,073.84	0.23%
Stair A 1,790.02 0.03% Hallway 6,987.57 0.12% Area: Apartment G 2,780.94 0.05% Area Subtotal: Apartment G 2,780.94 0.05% Area Subtotal: Fourth Floor 13,073.84 0.23% Area: Fifth Floor 5tair A Hall 682.19 0.01% Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Area: Fourth Floor		
Hallway 6,987.57 0.12% Area: Apartment G	Stair A Hall	1,515.31	0.03%
Area: Apartment G 2,780.94 0.05% Area Subtotal: Apartment G 2,780.94 0.05% Area Subtotal: Fourth Floor 13,073.84 0.23% Area: Fifth Floor Stair A Hall 682.19 0.01% Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Stair A	1,790.02	0.03%
Back Bedroom 2,780.94 0.05% Area Subtotal: Apartment G 2,780.94 0.05% Area Subtotal: Fourth Floor 13,073.84 0.23% Area: Fifth Floor 682.19 0.01% Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Hallway	6,987.57	0.12%
Area Subtotal: Apartment G Area Subtotal: Fourth Floor Area: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor 2,780.94 0.05% 682.19 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Area: Apartment G		
Area Subtotal: Fourth Floor Area: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor Area Subtotal: Fifth Floor 2,472.21 0.04%	Back Bedroom	2,780.94	0.05%
Area: Fifth Floor Stair A Hall Stair A Area Subtotal: Fifth Floor 2,472.21 0.04%	Area Subtotal: Apartment G	2,780.94	0.05%
Stair A Hall 682.19 0.01% Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Area Subtotal: Fourth Floor	13,073.84	0.23%
Stair A 1,790.02 0.03% Area Subtotal: Fifth Floor 2,472.21 0.04%	Area: Fifth Floor		
Area Subtotal: Fifth Floor 2,472.21 0.04%	Stair A Hall	682.19	0.01%
-,	Stair A	1,790.02	0.03%
CORALR-04-15-01 3/26/2018 Page: 4	Area Subtotal: Fifth Floor	2,472,21	0.04%
	CORALR-04-15-01	3/26/2018	Page: 4


Area: Sixth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Sixth Floor	2,472.21	0.04%
Area: Seventh Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Seventh Floor	2,472.21	0.04%
Area: Basement		
Stairs to Basement	2,669.74	0.05%
Area Subtotal: Basement	2,669.74	0.05%
Area: Eighth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Eighth Floor	2,472.21	0.04%
Area: Ninth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Ninth Floor	2,472.21	0.04%
Area: Tenth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Tenth Floor	2,472.21	0.04%
Area: Eleventh Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Eleventh Floor	2,472.21	0.04%
Area: Twelfth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Twelfth Floor	2,472.21	0.04%
Area: Thirteenth Floor		
CORALR-04-15-01	3/26/2018	Page: 4

Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Thirteenth Floor	2,472.21	0.04%
Area: Fourteenth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Fourteenth Floor	2,472.21	0.04%
Area: Fifteenth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Fifteenth Floor	2,472.21	0.04%
rea: Sixteenth Floor		
Stair A Hall	682.19	0.01%
Stair A	1,790.02	0.03%
Area Subtotal: Sixteenth Floor	2,472.21	0.04%
Electrical	214,135.00	3.75%
Exterior/General	13,500.00	0.24%
Stairway	660,624.09	11.58%
Demolition	1,260,816.32	22.10%
Left Elevation	1,042,995.12	18.28%
HVAC	541,367.36	9.49%
Debris Removal	96,000.00	1.68%
Scaffolding	512,500.00	8.98%
Post Construcion Clean Up	314,620.80	5.52%
Off Site Storage	24,765.16	0.43%
Site Work/Excavation	125,000.00	2.19%
Concrete Foundation	28,500.00	0.50%
General Conditions	788,081.60	13.82%
ubtotal of Areas	5,704,488.71	100.00%
	5,704,488.71	100.00%

Recap by Category


O&P Items		Total	%
CLEANING		316,339.02	4.26%
CONCRETE & ASPHALT		191,450.36	2.58%
CONTENT MANIPULATION		246.26	0.00%
CONT: PACKING,HANDLNG,STORAGE		24,765.16	0.33%
GENERAL DEMOLITION		1,444,034.35	19.44%
DOORS		8,850.00	0.12%
DRYWALL		47,674.83	0.64%
ELECTRICAL		214,135.00	2.88%
HEAVY EQUIPMENT		48,750.00	0.66%
FLOOR COVERING - STONE		803.43	0.01%
FLOOR COVERING - VINYL		198.94	0.00%
FINISH CARPENTRY / TRIMWORK		629.62	0.01%
FINISH HARDWARE		10,333.50	0.14%
FIRE PROTECTION SYSTEMS		25,917.36	0.35%
FRAMING & ROUGH CARPENTRY		57,093.60	0.77%
HAZARDOUS MATERIAL REMEDIATION		56,416.40	0.76%
HEAT, VENT & AIR CONDITIONING		515,450.00	6.94%
INSULATION		9,555.84	0.13%
LABOR ONLY		716,081.60	9.64%
LIGHT FIXTURES		13,807.44	0.19%
MOISTURE PROTECTION		1,421.28	0.02%
PAINTING		70,849.97	0.95%
ROOFING		784,212.66	10.56%
SCAFFOLDING		495,000.00	6.66%
STEEL COMPONENTS		560,889.87	7.55%
WINDOW TREATMENT		82.22	0.00%
O&P Items Subtotal		5,614,988.71	75.60%
Non-O&P Items		Total	%
PERMITS AND FEES		72,000.00	0.97%
SCAFFOLDING		17,500.00	0.24%
Non-O&P Items Subtotal		89,500.00	1.21%
O&P Items Subtotal		5,614,988.71	75.60%
Overhead @	10.0%	561,499.17	7.56%
Profit @	10.0%	561,499.17	7.56%
Total Tax(Rep-Maint) @	8.875%	599,529.11	8.07%
Total		7,427,016.16	100.00%

Basement






Main Level






Second Floor




Second Floor

Third Floor




Third Floor

Fourth Floor




Fourth Floor

Fifth Floor






Sixth Floor




Sixth Floor

Seventh Floor




Seventh Floor

Eighth Floor




Eighth Floor

Ninth Floor




Î Ninth Floor

Tenth Floor



Tenth Floor


Thirteenth Floor



Thirteenth Floor


Thirteenth Floor

Eleventh Floor




Eleventh Floor

Fourteenth Floor




Twelfth Floor




welfth Floor

Fifteenth Floor



Fifteenth Floor

Sixteenth Floor



Sixteenth Floor